

# **ENGINEERING CHANGE NOTICE** **DART AEROSPACE LTD**

Date: 12.02.29	Job No.: RD3383	ADR Yes/No: N	ADR Date:	ECN #: 12- 537
Product No.: D350-567-141		Created By: RF	Approved By:	
Product Name: Window Close-out Kit		Checked By:		

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL/JLM	MF 12.03.07
Purchasing Coord.	Y	CL	CL 12.03.06
Production Engineering Coord.	Y	EC	EA 12.03.06

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	N		
Customer Technical Support	Y	MB/DS	12.03.05
Marketing	Y	SW	SW 12.03.06
Customer Order Processing	N		

**Reason for Change:** Revise DSI 9590 per CHL after first set install.

**Documents Affected:**  
MDL-D350-567 Rev. H  
DSI 9590 Rev. B  
D4434 Rev. B  
D4435 Rev. B

**PARTS MUST COMPLY** ☒ **PREVIOUS PARTS SATISFACTORY** ☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	RF	MDL-D350-567 Rev. H	
6	Update Product Compatability Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	Y	KJ		12.03.05
11	Update Product Specification Files	Y	KJ		12.03.02
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		12.03.02
13	Update Document Record (DR)	N			
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	N			
17	Update / Verify ARC Database	<del>N</del>	<del>KJ</del>		
18	Create / Update Change Record Form / Item Card Database	Y	KJ	D350-567-141 at CHG 002	12.03.02
19	Create / Update PPP's	Y	KJ		12.03.05
20	Red Decals required?	Y	KJ		12.03.05
21	Update Document Control Database / Laminated Dwgs	N			
22	Update Grey Project / Electronic Binder PDF Files	Y	KJ		12.03.05
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		12.03.05
24					

**Description / Action:**  
Update BOM/routing for D4434 Rev. B, D4435 Rev. B  
D350-567-141 @ CHG 002  
The following dxf. files have been change D4434-9F; D4435-9F  
Update BOM for D350-567-141 per DSI 9590 Rev. B

ECN Verified & Complete: Date: 12/13/29